

00-59



Michael F. Del Casino
Regulatory Division Manager

Suite 1000
1120 20th Street, N.W.
Washington, DC 20036
202 457-2023
FAX 202 457-2165

May 17, 2000

Mr. Dale Hatfield
Chief, Office of Engineering and Technology
Federal Communications Commission
2000 M Street NW, Suite 480
Washington, DC 20554

Dear Mr. Hatfield:

As required by Part 63.100(a) of the Commissions Rules, AT&T hereby files its Final Service Disruption Report for an AT&T network outage.

1. DATE / INCIDENT LOCATION TIME:

April 17, 2000 12:30 PM PDT

2. GEOGRAPHICAL AREA AFFECTED:

Benbolt, CA

3. CUSTOMERS AFFECTED (APPROXIMATELY):

32,131 (based on blocked calls)

4. TYPES OF SERVICES AFFECTED:

Toll Access and Toll Completing

5. DURATION OF OUTAGE:

3 Hours and 26 Minutes

6. BLOCKED CALLS:

96,392

7A. CAUSE OF INCIDENT:

This incident was caused by an accumulation of rainwater in the waveguide equipment serving AT&T's Digital Radio system. Several days prior to this incident, Pacific Bell was performing a work activity, and erroneously removed dehydrator equipment that provided continuous dry air pressure to both Pacific Bell and AT&T equipment. Without constant air pressure on the waveguide, rainwater from a storm on April 17th entered the antenna, accumulated in the waveguide and blocked the radio signal, thereby failing service.

7B. EQUIPMENT NAME / TYPE:

Radio Equipment

7C. PART OF NETWORK:

Reno, NV – South Tahoe, CA

8. RESTORATION METHODS:

The On-Site Work Force technician drained the water from the waveguide and service was restored. The technician re-installed the dehydrator equipment to provide the necessary dry air pressure to the waveguide.

9. STEPS TO PREVENT REOCCURRENCE:

Since AT&T and Pacific Bell are tenants in the building owned and operated by American Tower Corporation (ATC), AT&T no longer controls the keys, access or security for this site. The master lease agreement with ATC does not require prior notification for maintenance work associated with other tenants. Therefore, a local agreement has been negotiated between Pacific Bell and AT&T to notify each other whenever work is to be performed at Ben Bolt, CA that could have a potential impact on equipment and services.

10. APPLICABLE BEST PRACTICES:

AT&T has reviewed the seven network reliability areas deemed highest priority in Network Reliability: A Report to the Nation, June 1993. Although there were no specific Best Practices referenced that were applicable to the root cause of this incident, AT&T continues to partner with leased suppliers in efforts to reduce potential service disruptions as mentioned above.

Sincerely,

A handwritten signature in black ink, appearing to read "M. J. [unclear]", is written over a horizontal line.

~~This form should be sent for the following circumstances:~~

B/C 90,000 - 149,999 3 days

B/C 150,000 & greater 120 minutes

00-54

AT&T**Initial Service Disruption Report**

FAX TO: FCC WATCH OFFICE, WASHINGTON, DC

202-632-6975 Voice

202-418-2812 FAX

ALTERNATE FCC WATCH OFFICER

202-418-2813 FAX

1.	Date/Time of Incident	<u>4-17-2000 at 1230 MST</u>
2.	Geographic area affected	<u>Reno, NV - South Tahoe, CA</u>
3.	Customers affected (est)	<u>32,131</u>
4.	Types of service affected	<u>Toll Connect</u>
5.	Duration of outage	<u>3 hrs 35 min</u>
6.	Blocked calls (est)	<u>96,392</u>
7a	Cause of incident	<u>Water in waveguide</u>
7b	Equipment name/types	<u>Radio equipment</u>
7c	Part of network affected	<u>Ben Bolte CA</u>
8.	Restoration methods used	<u>N/A</u>
9.	Steps to prevent recurrences	<u>N/A</u>
AT&T contact person:		<u>Mike DelCasino</u>
Telephone number:		<u>202-457-2023</u>
Date/Time of report:		